

Инструкция по сборке
E2009.0000.0000





Таблица 1 — Составные части оборудования

 E2009.0011.0000 — 1 шт	 E2009.0012.0000 — 1 шт	 E2009.0013.0000 — 1 шт	 E2009.0014.0000 — 1 шт	 E2009.0015.0000 — 2 шт
 E2009.0000.S001 — 1 шт	 E2009.0000.S002 — 1 шт	 0000.0000.0691 — 4 шт	 STP.0104 (Заглушка круглая, пластик., Ø40 мм) — 4 шт	 BO08.030.A2.D7380 (Болт полусфер., с внутр. шестигр., нерж., M8×30, DIN 7380) — 8 шт
 NT12.D985 (Гайка с пластиковой вставкой, M12, DIN 985) — 4 шт	 SH12.100.D571 (Винт самонар., с шестигр. головкой, 12×100, DIN 571) — 6 шт	 WP08.A2.D125 (Шайба плоская, нерж., M8, DIN 125) — 8 шт	 WP12.A2.D9021 (Шайба увеличенная, нерж., M12, DIN 9021) — 4 шт	 WS08.A2.D127 (Шайба гроверная, нерж., M8, DIN 127) — 8 шт




Рисунок 1




Рисунок 2




Рисунок 3