

Инструкция по сборке  
**E6309.0000.0000**








Таблица 1 — Составные части оборудования

				
0000.3208.0000 — 1 шт	E6309.0001.0000 — 1 шт	E6309.0002.0000 — 1 шт	E6309.0005.0000 — 1 шт	E6309.0000.S007 — 1 шт
				
E6309.0000.S008 — 1 шт	E6309.0000.S011 — 1 шт	E6309.0000.S012 — 1 шт	E6309.0000.S015 — 1 шт	E6309.0000.S016 — 1 шт
				
0000.0000.0584 — 12 шт	STP.0104 (Заглушка круглая, пластик., Ø40 мм) — 24 шт	NT12.D985 (Гайка с пластиковой вставкой, M12, DIN 985) — 24 шт	SH12.100.D571 (Винт самонар., с шестигр. головкой, 12×100, DIN 571) — 18 шт	SO08.080 (Винт самонар., полусфер., с пресс-шайбой, TORX, 8×80) — 4 шт



WP12.A2.D9021 (*Шайба увеличенная, нерж., M12, DIN 9021*) — 24 шт




Рисунок 1




Рисунок 2




Рисунок 3




Рисунок 4