









Инструкция по сборке
8018.0000.0000



Таблица 1 — Составные части оборудования

				
0000.0413.0000 — 6 шт	8018.0005.0000 — 1 шт	0000.0000.6324 — 1 шт	0000.0000.6325 — 3 шт	0000.0000.6326 — 3 шт
				STP.0004 (Колпачок защитно-декор., пластик., M10, Ø37 мм) — 18 шт
0000.0000.7410 — 6 шт	8018.0000.0011 — 1 шт	8018.0000.0012 — 1 шт	8018.0000.0014 — 1 шт	
				
STP.0005 (Заглушка колпачка защитно-декор., пластик., M10, Ø37 мм) — 18 шт	STP.0013 (Заглушка квадратная, пластик., 40×40 мм) — 6 шт	BF10.070.D603 (Болт меб., с квадр. подголовником, M10×70, DIN 603) — 12 шт	BF10.090.D603 (Болт меб., с квадр. подголовником, M10×90, DIN 603) — 6 шт	NF10.D6923 (Гайка с фланцем, M10, DIN 6923) — 18 шт



SS05.050.D7982 (*Винт самонар.,
потай., 5×50, DIN 7982*) — 10 шт




Рисунок 1






Рисунок 2



0000.0411.0000

ВИД А





Рисунок 3




Рисунок 4