

Инструкция по сборке
8016.0000.0000













Таблица 1 — Составные части оборудования

				
0000.0413.0000 — 2 шт	0000.0416.0000 — 2 шт	0000.0000.6324 — 2 шт	0000.0000.6325 — 1 шт	0000.0000.6326 — 2 шт
				
0000.0000.6327 — 1 шт	0000.0000.7410 — 2 шт	8016.0000.0002 — 1 шт	8016.0000.0005 — 1 шт	8016.0000.0006 — 1 шт
				
STP.0004 (Колпачок защитно-декор., пластик., M10, Ø37 мм) — 10 шт	STP.0005 (Заглушка колпачка защитно-декор., пластик., M10, Ø37 мм) — 10 шт	STP.0013 (Заглушка квадратная, пластик., 40×40 мм) — 4 шт	BF10.070.D603 (Болт меб., с квадр. подголовником, M10×70, DIN 603) — 6 шт	BF10.090.D603 (Болт меб., с квадр. подголовником, M10×90, DIN 603) — 4 шт



NF10.D6923 (Гайка с фланцем, M10, DIN 6923) — 10 шт



SS05.050.D7982 (Винт самонар., потай., 5×50, DIN 7982) — 4 шт




Рисунок 1




Рисунок 2




Рисунок 3